



SCHEMA DI MONTAGGIO /
ASSEMBLY INSTRUCTIONS /
MONTÁŽNY MANUÁL

FADE CHAIR
gambe in metallo verniciato
Stoli ka Fade

STOLI KA FADE

Elementi / Components / Obsah balenia




(A)

4x

Vite M6 x 30 mm

M6 x 30 mm screw

Skrutka M6 x 30 mm



(B)

1x

Chiave a brugola da 4 mm.


Allen wrench 4 mm.

Imbusový k ú 4 mm.

1° STEP / ÉTAPE / KROK

Ribaltare la scocca dell'articolo. *Turn the article's shell upside down.*

Oto te sedadlo dolu hlavou.




2° STEP / ÉTAPE / KROK

Appoggiare le gambe sul fondo della scocca dell'articolo.

Place the legs on the bottom of the body of the article.

Umiestnite nohy na spodnú časť tela sedadla.



ⓘ **Attenzione / Attention / Upozornenie:**

Il lato più inclinato va posizionato in corrispondenza dello schienale.

Position the more sloping side at the backrest.


Strmšiu časť nôh smerujte k operadlu.

3° STEP / ÉTAPE / KROK

Fissare le gambe alla scocca con le 4 viti in dotazione (A), con l'ausilio della chiave a brugola (B).

Fix the legs to the bodyshell using the 4 screws (A) (included), using an Allen key (B).

Upevnite nohy na sedadlo pomocou 4 skrutiek (A) a priloženého imbusového k ú (B).



4° STEP / ÉTAPE / KROK

Capovolgere la sedia.

Return the chair to the right way up.

Oto te stoli ku.

